


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350 °C, 50 Watt max. and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



THIS DRAWING MAY NOT BE COPIED OR REPRODUCED IN ANY WAY, AND MAY NOT BE PASSED ON TO A THIRD PARTY WITHOUT WRITTEN PERMISSION.

WRATTEN PERMISSION. scale: 3:1 CAD DRAWING BY HAND tolerance material: SEE SHEET 1 dim. in mm date title: RECOMMENDED PANEL CUT-OUT D-SUB MALE HD 26pos. SOLDER CUP appd. 29.07.14 Lehmenkühler with threaded lock and 4-40 UNC stud bolt ALTER (dwg no: DIN-АЗ 15K1A1528 N Original sh: 2/2 description part no: SEE SHEET 1 date

Directive 2002/95/EC RoHS compliant

4