



Product Change Notification - SYST-27GBBQ522

Date:

29 Nov 2018

Product Category:

Ethernet Switches

Affected CPNs:



Notification subject:

ERRATA - KSZ9897S Silicon Errata & Data Sheet Clarification Errata Document Revision

Notification text:

SYST-27GBBQ522

Microchip has released a new DeviceDoc for the KSZ9897S Silicon Errata & Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [KSZ9897S Silicon Errata & Data Sheet Clarification](#).

Notification Status: Final

Description of Change: Added new errata: - "Transmission halt with late collisions" and "LEDx_0 in Single-LED Mode does not indicate link activity"

Pre Change: N/A

Post Change: N/A

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 23 Aug 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed..

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[KSZ9897S Silicon Errata & Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

KSZ9897STXC

KSZ9897STXC-TR

KSZ9897STXI

KSZ9897STXI-TR