

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

PRODUCT DISCONTINUANCE NOTICE

PDN #: M000997N

DATE: 15-Jun-2020

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX1127EGK+	N/A			Part reactivated from prior notice: M000872I
Reactivation	MAX1184ECM+	N/A			Part reactivated from prior notice: M000907I
Reactivation	MAX19588ETN+	N/A			Part reactivated from prior notice: M000841
Reactivation	MAX2140ETH+	N/A			Part reactivated from prior notice: M000969I
Reactivation	MAX3802UTK+	N/A			Part reactivated from prior notice: M000989N
Reactivation	MAX5874EGK+	N/A			Part reactivated from prior notice: M000872I
Reactivation	MAX5875EGK+	N/A			Part reactivated from prior notice: M000812
Reactivation	MAX5878EGK+	N/A			Part reactivated from prior notice: M000872I
Reactivation	MAX5883EGM+	N/A			Part reactivated from prior notice: M000812
Reactivation	MAX5884EGM+	N/A			Part reactivated from prior notice: M000812
Reactivation	MAX5885EGM+	N/A			Part reactivated from prior notice: M000812
Reactivation	MAX5886EGK+	N/A			Part reactivated from prior notice: M000872I
Reactivation	MAX5887EGK+	N/A			Part reactivated from prior notice: M000812
Reactivation	MAX5888AEGK+	N/A			Part reactivated from prior notice: M000872I
Reactivation	MAX5888EGK+	N/A			Part reactivated from prior notice: M000872I
Reactivation	MAX5889EGK+	N/A			Part reactivated from prior notice: M000812
Reactivation	MAX5895EGK+	N/A			Part reactivated from prior notice: M000872I