



Expertise Applied | Answers Delivered

Littelfuse, Inc.
8755 West Higgins Road, Suite 500
Chicago, IL 60631 USA
www.littelfuse.com

Product Change Notice (PCN)

January 28, 2021

Product Discontinuation Notice for Select NTC Material Curves

Dear Valued Customers and Distributors:

Littelfuse, Inc. would like to inform you of the discontinuation of select NTC material curves due to low demand for more than four years.

- We can only accept a last time purchase order for these products until **April 30, 2021**

Please see Appendix A of this letter for the list of part numbers being discontinued. Unfortunately, there are no replacements.

Please contact your Littelfuse sales representative to make arrangement for a last time buy order for the affected part numbers. All last time buy orders will be **non-cancelable** and **non-returnable**. Last time buy orders will be subject to product availability. Not all products may be available in supply to support last time buys.

This notification is for your information and acknowledgement. Please respond to us by **February 28, 2021** to acknowledge receipt and understanding of this discontinuation notice. If we do not hear from you by the above-mentioned date, we will expect that this discontinuation notice has been accepted and that no further action is required.

Should you have any questions or require additional information, please contact your local Littelfuse sales representative.

Sincerely,

Tim Patel
Global Product Manager – Temperature Sensors
Industrial Business Unit
Littelfuse, Inc.



Expertise Applied | Answers Delivered

Product Discontinuation Notice for Select NTC Material Curves
Appendix A – List of Affected Littelfuse Part Numbers

Page A1 of 1

Littelfuse Part Numbers			
AT303H16	LC403H3F	USP15916	USP7039
BC101C4K	LC495Z5J	USP16957	USP7806
BC102E2K	LC985Z5J	USP16957-1	USP8712
BC104V7J	PT103N4	USP17530	USX0934-2
BC291J4G	PT104L3	USP17903	USX1046
BC501E3K	TC103H2F	USP18803	USX1123
DC203V4K	TC103H3F	USP1979	USX1740
KC203N3F	TC403H2P	USP3423	USX1790
LC103N3H	USP10578	USP4065	USX1862
LC104Q2J	USP11600	USP4331	USX3002
LC104V3F	USP11799-1	USP4548	USX3435
LC124V4J	USP12646	USP5082	
LC202G4H	USP13148	USP5321	
LC282N5H	USP15509	USP5985	

Note: Part numbers may or may not be followed by “dash” suffixes depending on product (e.g., USP11799-1, USP11799-2, etc.)