



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000815

DATE: 04-Dec-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX8563EEE+T	N/A			Part reactivated from prior notice: M000869I
Reactivation	MAX88200EFD+	N/A			Part reactivated from prior notice: M000810
Reactivation	MAX88200EFD+T	N/A			Part reactivated from prior notice: M000810
Reactivation	MAX8967EWV+	N/A			Part reactivated from prior notice: M000852I
Lead-Free Conversion	MAX1819EBL25-T	MAX1819EBL25+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX3204EEBT-T	MAX3204EEBT+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX3378EEBC-T	MAX3378EEBC+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX4163EBL-T	MAX4163EBL+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX4762EBC-T	MAX4762EBC+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX6400BS26-T	MAX6400BS26+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX6400BS30-T	MAX6400BS30+T	04-Jun-2016	04-Dec-2017	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX14570EZT+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX14583EEWE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX14650EZA+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX14650EZA+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX15014BATX+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX15015AATX+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX15017BATX+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX16935RAUE/V+GE	MAX16935RAUE/V+	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX16935RAUE/V+TGE	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX16989ATJA/V+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX16989ATJB/V+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX17823GCB/V+	MAX17823BGCB+	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX17823GCB/V+T	MAX17823BGCB+	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX20056AUG/V+G2Z	N/A	04-Jun-2016	03-Dec-2017	The part was not released
Discontinuance	MAX20070GTJ/V+G2Z	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Jan-2016

Discontinuance	MAX21215ELD+	N/A	04-Dec-2015	04-Dec-2015	The part was not released
Discontinuance	MAX21215EVBRD#	N/A	04-Dec-2015	04-Dec-2015	EVKIT is No Longer Supported
Discontinuance	MAX21215EVKIT#	N/A	04-Dec-2015	04-Dec-2015	EVKIT is No Longer Supported
Discontinuance	MAX2205EBS+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2205EBS+T10	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2206EBS+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2206EBS+T10	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2207EBS+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2208EBS+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2209EBS+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2209EBS+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2209EBS+T10G45	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2209EBS+TG45	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2240EBL+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2240EBL+TW	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX2242EBC+TW	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3204EEWT+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3204EEWT+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3228EBV-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3228EEBV-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3229EBV-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3229EEBV-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3230EEBV-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3231EEBV-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX3345EEBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3346EEBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3349EEBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3349EEBE+TC69	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX3395EEBC+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4000EBL+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4000EBL+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4001EBL+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4001EBL+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4003EBL+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4003EBL+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4131EBT+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Jan-2016

Discontinuance	MAX4323EBT+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4691EBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4692EBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4693EBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX4694EBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77311EWE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77601AEWJ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77611EWJ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77612AEXJ+	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77612AEXJ+W	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77660BEWV+	MAX77660AEWV+	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77663LEWJ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX77823QEWZ+	MAX77823EWZ+	04-Jun-2016	03-Dec-2017	The part was not released
Discontinuance	MAX77823QEWZ+T	MAX77823EWZ+T	04-Jun-2016	03-Dec-2017	The part was not released
Discontinuance	MAX77826QEWJ+	MAX77826EWJ+	04-Jun-2016	03-Dec-2017	The part was not released
Discontinuance	MAX77826QEWJ+T	MAX77826EWJ+T	04-Jun-2016	03-Dec-2017	The part was not released
Discontinuance	MAX8521EBX-T	N/A	04-Jun-2016	04-Dec-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX8674EWN+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8805WEREEE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8834ZEWP+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8939BEWV+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8939EWV+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8976EWA+	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8987EWQ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8987SEWQ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8991EWG+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8996EWZ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8996KEWZ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX8998EWQ+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX97003EWP+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9700AEBC+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9700DEBC+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9720AEBE+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX9796EBX+G45	N/A	04-Jun-2016	03-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX98096EWF+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
Discontinuance	MAX98506EWW+T	N/A	04-Jun-2016	04-Dec-2017	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Jan-2016

Discontinuance	MAX9875ERP+T	N/A	04-Jun-2016	04-Dec-2017	Part can no longer be manufactured
----------------	--------------	-----	-------------	-------------	------------------------------------