



# Product Discontinuance Notice - PDN 11\_0074 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

## PDN Title:

Discontinuance of Select AD9238 Products

**Publication Date:** 12-Sep-2011

**Last Time Buy Date:** 30-Nov-2011

**Last Time Ship Date:** 31-May-2012

## Reason For Discontinuance

An Assembly Supplier to ADI has announced the shutdown of the lead (Pb) finish line within 2011.

## Comments

RoHS compliant replacements are available to order.

**Supporting Documents**      None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

<b>Americas:</b>	PDN_Americas@analog.com	<b>Europe:</b>	PDN_Europe@analog.com	<b>Japan:</b>	PDN_Japan@analog.com
		<b>Rest of Asia:</b>			PDN_ROA@analog.com

## PDN 11\_0074 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
AD80078BSTRL	AD9238	AD9238BSTZRL-65	Yes	
AD9238BST-20	AD9238	AD9238BSTZ-20	Yes	
AD9238BST-40	AD9238	AD9238BSTZ-40	Yes	
AD9238BST-65	AD9238	AD9238BSTZ-65	Yes	
AD9238BSTRL-40	AD9238	AD9238BSTZRL-40	Yes	
AD9238BSTRL-65	AD9238	AD9238BSTZRL-65	Yes	

## Appendix A - PDN 11\_0074 Revision History

Rev	Publish Date	Rev Description
Rev. -	12-Sep-2011	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:338

Layout Rev:2

Parent DocId:None